



NOTE

1. Must remove harmful Burr.
2. Assembling counterparts should be no abnormality.
3. Apply general tolerances for unmarked tolerances.
4. Mass production after obtaining approval.

1	-	-	-	-	-	-
No	NAME	Q'ty	ERP CODE	SPEC	MATERIAL	SUPPLY
PART NAME	DIMENSION		MATERIAL	-	END FINISH	-
MODEL NAME	TCS-9500 ENCODER		SUPPLY	-	SCALE	UNIT
PART NO & DRAWING NO	-		Q'TY	-	REV NO.	-
DRAWN BY	CHECKED BY	APPROVED BY		MODIFIED BY		
J. I. YU	-	-		W. J. MOON		
2022. 06. 13.	-	-		2025. 05. 28.		

1 : 1

mm

1 / 1

A2

TRUEN

True Technology for Secure World